

Chautauqua Hall Repairs & Painting

Origination Year:	FY 2015/16	Program: Buildings and Grounds
Planned Comp Year:	FY 2016/17	
Department:	Public Works	Project Manager: Roque Pinheiro

Project Description/Scope/Purpose

This project consists of Interior and exterior repairs and painting of Chautauqua Hall. The Building has not had interior or exterior painting since 90's and the interior has been roughly 30 years. Interior and exterior painting is maintenance that needs to occur to ensure the longevity of structures and enables the structures to withstand daily use and weather conditions.

Project Evaluation and Analysis

This project has been evaluated by the Recreation Department and the Buildings and grounds Department.

Fiscal Impact

Proposed Fund/Account Numbers	FY 16/17	FY 17/18	FY 18/19	FY 19/20	FY 20/21	FY 21/22
	10,000					10,000

